

Primary Items

## Agility - Bridge

Manufactured by (Unknown)



**Risk level:**  
■ Low

✔ Risk score as low as possible

**Remedial tasks:**  
 2



**Standards:** ✔

EN 1176-1:2017  
 The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

### Maintenance Finding

**Description**

Cap missing.

**Tasks**

Replace.

**Note**

Various on underside.

**Risk level:**  
■ Very low

**Risk score:**  
■ 2

**Finding Photos**



Primary Items

Maintenance Finding

Description

Timber is decayed.

Tasks

Replace affected parts.

Risk level:

Low

Risk score:

6

Finding Photos



Primary Items

## Agility - Stepping Log

Manufactured by (Unknown)




**Standards:**

EN 1176-1:2017  
The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

### Maintenance Finding

**Description**

Timber is decayed.

**Tasks**

Read the notes for further action.

**Note**

Remove and make the ground level.

Risk level:  
 Low

Risk score:  
 6

**Finding Photos**



Primary Items

## Agility - Balance Log

Manufactured by (Unknown)



**Risk level:**  
■ Low

✔ Risk score as low as possible

**Remedial tasks:**  
 1

Free height of fall: 0.2m

Surface: Grass

**Standards:** ✔

EN 1176-1:2017  
 The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

### Maintenance Finding

**Description**

Timber is decayed.

**Tasks**

Check on a routine basis.

**Risk level:**  
■ Low

**Risk score:**  
■ 4

**Finding Photos**



Primary Items

## Carousel - Flush

Manufactured by Other



**Standards:** 

EN 1176-1:2017, EN 1176-5:2019

The item complies with the requirements of the relevant standards.  
The surfacing is not compliant with the requirements of the relevant standards.

Surface: Wet Pour  
at a depth of 20 mm

Primary Items

**Maintenance Finding**

**Description**

There is wear in the bearings.

**Tasks**

Monitor and replace when necessary.

**Note**

Some bearing wear, but the asset is operating fairly smoothly at the time of inspection. The rate of wear will depend upon the level of use. Monitor.

Risk level:

■ Very low

Risk score:

■ 2

**Finding Photos**



**Standard Compliance Finding**

**Description**

Insufficient protective surfacing extent has been provided.

**Tasks**

Read the notes for further action.

**Note**

Depth measured as 20 mm, with concrete beneath. The surface should provide adequate impact attenuation for a free height of fall of 1 m. The inspector considers it to be unlikely that the surface will provide this. Monitor, plan to replace this asset and its surfacing.

Risk level:

■ Low

Risk score:

■ 7

**Finding Photos**



Primary Items

HAGS

## Swing - Junior - 2 Bay 3 Seat

Manufactured by HAGS SMP



**Risk level:**  
Medium

**Risk score as low as possible**

**Remedial tasks:**  
 2



Surface: Rubber - Mulch - Bonded at a depth of 40 mm

**Standards:** ✔

EN 1176-1:2017, EN 1176-2:2017  
 The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

### Maintenance Finding



**Description**

Fixtures loose or missing.

**Tasks**



Tighten/replace.

**Note**



The indicated bolt was left finger tight only. Ensure that all other bolts have been properly tightened in accordance with the manufacturer's instructions.

**Risk level:**

Medium

**Risk score:**

8

**Finding Photos**



Primary Items **HAGS**

### Maintenance Finding

#### Description

Additional comments are noted below.

#### Tasks

Read the notes for further action.

#### Note

Grass matting present at the surface edges. Trip points not considered particularly significant at the time of inspection. Monitor.

Risk level:  
 Low

Risk score:  
 4

#### Finding Photos





Primary Items

HAGS

## Rocker - Sweeping Seesaw - Gyro Spiral

Manufactured by HAGS SMP



### Standards:

EN 1176-1:2017, EN 1176-6:2017

The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

Surface: Rubber - Mulch - Bonded at a depth of 40 mm

Primary Items

# Climber - Crow's Nest

Manufactured by Proludic Ltd



**Risk level:**  
Low

**Risk score as low as possible**

**Remedial tasks:**  
3



Surface: Grass Matting at a depth of 16 mm

**Standards:**

EN 1176-1:2017  
The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

## Maintenance Finding

**Description**

Fixtures loose or missing.

**Tasks**

Tighten.

**Note**

Various.

Risk level:

Low

Risk score:

4

**Finding Photos**



Primary Items

### Maintenance Finding

**Description**

Additional comments are noted below.

**Tasks**

Read the notes for further action.

**Note**

The surfacing is in good condition at the time of inspection. Monitor through the seasons.

Risk level:

See finding details

**Finding Photos**



### Maintenance Finding

**Description**

Exposed metal rope core(s).

**Tasks**

Read the notes for further action.

**Note**

Monitor for sharp strands breaking free, particularly at stress points.

Risk level:

Low

Risk score:

6

**Finding Photos**



Primary Items

HAGS

## Multiplay - Junior

Manufactured by HAGS SMP



### Standards:

EN 1176-1:2017

\* The item is not compliant with the requirements of the relevant standards. The surfacing meets with the requirements of the relevant standards.

Surface: Rubber - Mulch - Bonded at a depth of 40 mm

Primary Items NAGS

---

### Maintenance Finding

<p><b>Description</b></p> <p>✍ Fixtures loose or missing.</p> <p><b>Tasks</b></p> <p>✍ Tighten.</p> <p><b>Note</b></p> <p>✍ Two bolts found to be very loose. Ensure that all other fittings are properly tightened.</p>	<p><b>Risk level:</b></p> <p><span style="background-color: yellow; border: 1px solid black; padding: 2px;">Medium</span></p> <p><b>Risk score:</b></p> <p><span style="background-color: yellow; border: 1px solid black; padding: 2px;">8</span></p>
--	--

#### Finding Photos



### Standard Compliance Finding

<p><b>Description</b></p> <p>✍ Finger entrapment.</p> <p><b>Tasks</b></p> <p>✍ Eliminate the entrapment.</p> <p><b>Note</b></p> <p>✍ Top of the climbing wall. Modify the positions of the brackets to prevent the insertion of the 8 mm diameter finger rod.</p>	<p><b>Risk level:</b></p> <p><span style="background-color: lightgreen; border: 1px solid black; padding: 2px;">Low</span></p> <p><b>Risk score:</b></p> <p><span style="background-color: green; border: 1px solid black; padding: 2px;">4</span></p>
---	--

#### Finding Photos



Primary Items

MAGS

## Space Net - Central Post

Manufactured by Tayplay Ltd



### Standards:

EN 1176-11:2014, EN 1176-1:2017

The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

Surface: Rubber - Mulch - Bonded at a depth of 40 mm

Primary Items

# Agility Trail

Manufactured by Playdale Playgrounds Ltd



Surface: Grass

**Standards:**

EN 1176-1:2017

The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

NAGS

Primary Items

## Rocker - Elephant

Manufactured by Ledon A/S



Risk level: Low  
 Potential risk score reduction: 4  
 Remedial tasks: 3



Surface: Grass Matting at a depth of 16 mm

**Standards:**

EN 1176-1:2017, EN 1176-6:2017  
 The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

### Maintenance Finding

**Description**

Cap missing.

**Tasks**

Replace.

Risk level: Low  
 Risk score: 6

**Finding Photos**





Primary Items NAGS

---

### Maintenance Finding

---

**Description**

Fixtures loose or missing.

**Tasks**

Read the notes for further action.

**Note**

Unusual movement in bracket. Dismantle, investigate, repair as appropriate.

Risk level:

■ Low

Risk score:

■ 7

**Finding Photos**



### Maintenance Finding

---

*Handwritten mark*

**Description**

Item is bent.

**Tasks**

Repair.

Risk level:

■ Low

Risk score:

■ 6

**Finding Photos**



Primary Items

## Rocker - Seesaw

Manufactured by Ledon A/S



Surface: Grass Matting at a depth of 16 mm

**Standards:**

EN 1176-1:2017, EN 1176-6:2017

The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

Primary Items

## Multiplay - Toddler

Manufactured by Playdale Playgrounds Ltd



**Standards:** ✓

EN 1176-1:2017  
The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

Surface: Grass Matting at a depth of 16 mm