


# **Safety Inspection Report**

Post-installation Inspection

# **The Rype New Play Area**

Lydd Town Council

09 February 2023



Playsafety Ltd is licensed by RoSPA to trade as RoSPA Play Safety



# Safety Inspection Report

## Post-installation Inspection

Site name: Date of inspection: 09 February 2023 Inspector:

The Rype New Play Area **Chris Taylor** 





Playsafety Ltd is licensed by RoSPA to trade as RoSPA Play Safety

#### How to read your report

The assets on site are categorised as Ancillary Items or Play Items, and listed under those headings.

Each item is listed in the style shown in the image below, which contains labels to aid interpretation as follows:

- 1) The name of the asset
- 2) The manufacturer of the asset, if known,
- The innate or default risk score of the asset, assuming it has no faults and complies with standards,
- The actual risk score of the asset at the time of inspection, being the highest of the finding risks or the innate risk,
- A statement about whether the item complies with the appropriate standards, including the names of those standards,
- 6) Details about findings, if any, including what is wrong (Description), what to do about it (Tasks), notes to aid understanding (Notes), and photograph(s) of the issue.





# **The Overall Site**




## **Maintenance Finding**

Description	Risk level:
Additional comments are noted below.	Low
Tasks	Risk score:
Read the notes for further action.	6
Note	A MARTINE LAW

The inspector recommends installing fencing to reduce the risk of dogs gaining entry. Benches should be a minimum of 1 m from the fencing. Bins should be between 2 m & 3 m from the benches / gates. Appropriate signage should be provided at all entrances.

Photo not possible





### **Maintenance Finding**

The inspector believes that the indicated locations are most suitable for the potential toddler swings. Swings should be positioned away from the main routes of users.

**Finding Photos** 





# Ancillary Items Seating - Benches x 3 **Risk level:** innute risk level (ctual Low 11530 Potential risk score reduction: (evel 1 Remedial tasks: 100 2 **Maintenance Finding** Description **Risk level:** Fixtures loose or missing. Low Tasks Risk score: Tighten. 4 **Finding Photos** A3 inspection 90000223664. Report produced on 09/02/2023 at 12:21:19



Inspection \$10000223664. Report produced on 09/02/2023 at 12:21:19

**A**4

### Ancillary Items

# **Litter Bin**



## **Maintenance Finding**




#### Note

Holes developing. The inspector recommends replacement. It may be possible to extend the life of the asset with suitable repairs.

### **Finding Photos**









Dog ban signage provided, but not in a particularly prominent location. The inspector recommends installing a fence and positioning appropriate signage at the entrances.

### **Finding Photos**



A6

Inspection \$10000223664. Report produced on 09/02/2023 at 12:21:19

Ancillary Items

84





Inspection 510000223664. Report produced on 09/02/2023 at 12:21:19